



1100 W Cambridge Circle Drive, Suite 700
Kansas City, Kansas 66103
913.627.9040

DAILY FIELD REPORT

CLIENT: Streets of West Pryor, LLC
3501 West 147th Street
Leawood, Kansas 66224

PROJECT: Streets of West Pryor
Lee's Summit, Missouri

ATTN: Dave Olson

DATE: 10/9/19

WEATHER: Light Rain

CFS
PERSONNEL: M. Simpson

TEMPERATURE: 50-60

REPORT #: 19-1066-dr- 81

TYPE OF SERVICE BEING PERFORMED

SOILS COMPACTION MONITORING

DEVIATION FOUND: NO

DEVIATION CORRECTED:

ORIGINAL DEVIATION DATE:

WORK ACCOMPLISHED THIS DATE:

- Monitored placement and compaction of fill for
 - 1.) Observed the 24" HDPE trenching from C-10.1 to C-10.2, 40' linear feet, -9' elevation to finish grade adequate compactive effort observed.
 - 2.) Retaining wall Q – from station 0+74 to 4+26, elevation 988.0 to 990.0, all work completed today was per job site specifications
 - 3.) Rock removal for trenching of storm sewer line B, North from B-4.
 - 4.) Lowenstein drive received Geogrid and 6" of base rock from station 40+50 to station 36+00, all work today was per job site specifications and adequate compaction observed.