CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192047

Address: 300 SW BLUE PKWY, Unit:B, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Gas Piping Inspection - John Borns Failed Wednesday, October

Commercial 16, 2019

Corrective Action Required:

1 Misc IFGC 407.2 & 415; IRC G2423 SUPPORT OF HORIZONTAL RUNS OF RIGID STEEL

PIPING: SPACING OF BLOCKS/HANGERS --: 1/2" PIPE -- 6' MAX SPACING; 3/4" OR 1" PIPE -- 8' MAX SPACING; 1-1/4" OR LARGER PIPE -- 10' MAX SPACING.

SUPPORT SUPPORT WITHIN 18" OF ENDS, 90'S, TEES, AND JOINTS.

Corrective Action Required:

2 Misc IFGC 408 GAS PIPING DRIP/DIRT LEG: MUST BE AT ELEVATION TO HAVE CAP

REMOVED FOR CLEANING AND REPLACED. BOTTOM OF NIPPLE TO BE NO

CLOSER TO ROOF THAN DEPTH OF CAP + 1/4".

Corrective Action Required:

3 Misc IFGC 404.8: METALLIC PIPING EXPOSED TO WEATHER MUST BE PERMANENTLY

PROTECTED WITH PAINT OR BY OTHER APPROVED MEANS. <u>PAINT 100% OF</u>

STEEL PIPE INCLUDING AT SUPPORTS. SEE GAS PIPING AT METER AND

ROOFTOP.

Comments: