CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20190043

Address: 1912 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Plot Plan Inspection Steve Conrick Passed Friday, October 18,

2019

Comments:

This is an area where it is not possible to meet 2%. From the ground shouts, the swale is at roughly 1.7%. The swale looks good and the builder even added a gravel bed.