CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172513 Address: 229 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspector:	Outcome:	Date:
Mark Harding	Failed	Wednesday, October 23, 2019
RC- throughout approved.		
Nail pattern all units approved.		
Failed- see red marks in west corridor 1st & 2nd floor. Screw pattern , screws to close to edge of rock, screw pattern over 16" O>C> on studs. Screw pattern anywhere from 10" to 14". Remove sheetrock on HVAC in corridor for inspection of firewall.		
	Mark Harding RC- throughout approv Nail pattern all units ap Failed- see red marks in to close to edge of rock anywhere from 10" to	Mark Harding Failed RC- throughout approved. Nail pattern all units approved. Failed- see red marks in west corridor 1st & 2r to close to edge of rock, screw pattern over 10 anywhere from 10" to 14".

Recall when ready.

Comments: