

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20192955
Address: 4415 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Brandon Kalwei	Failed	Thursday, October 24, 2019

Corrective Action Required:

- | | | |
|---|------|---|
| 1 | Misc | <ul style="list-style-type: none">- fire block dead space at top plate, west wall- fire block at top plate NW corner- protect plumbing near stop plate in storage area, west wall- fire block dead space north wall near stairs- fire block double wall vertically, north side wall- protect vent stack piping east wall at top and bottom plate, turn out clean out for accessibility- fire block south double wall in bedroom vertically- need smoke/co detector inside bedroom and smoke detector out side of bedroom- be sure in sheet rock underneath stairs |
|---|------|---|

Do not insulate

Comments: