CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172509

Address: 217 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes John Borns Failed Friday, November 01,

Commercial 2019

Corrective Action Required:

1 Misc COMPLETE ALL WORK AT RISER ROOM INCLUDING FIRESTOPPING OF RATED

ASSEMBLIES

Corrective Action Required:

2 Misc IT ROOM:

- PLUG UNUSED OPENING AT PANEL POSITION #41 - OPENING ABOVE DOOR IN RATED WEST WALL?

Corrective Action Required:

3 Misc BALCONY GUARD POST BASES: CHECK ALL FOR MISSING OR LOOSE SCREWS

Corrective Action Required:

4 Misc NEC 314-20; IRC E3906.5-6 SET-BACK OF ELECTRICAL RECEPTACLE / SWITCH

BOXES: 1/4" MAXIMUM SET-BACK @ NON-COMBUSTIBLE SURFACES. CHECK

ALL AT KITCHEN BACKSPLASH.

Corrective Action Required:

5 Misc SOME ELECT RECEPTS NOT SOLID TO BOX -- MARKED WITH TAPE

Comments: OBTAIN APPROVAL FROM CIVIL INSPECTOR.