CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20181907 Address: 249 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspect	tion:	Inspector:	Outcome:	Date:
Footing	g Inspection - Commerc	ial Mark Harding	Partial	Friday, November 01, 2019
Correct	ive Action Required:			
1	Misc	Lower exterior footing ,		
	ufer needs to be installed in upper footings			
Partial	Correction:			
2	Misc	OK TO POUR WHEN READ	Y FLOOR SLAB WITH SLAB TH	IICKENING AT WALL LINES
		AT:		
		SOUTH AND NORTH ONE-	THIRDS AFTER SLAB DOWELS	ARE BENT UP INTO SLAB
		THICKNESS		

Comments: