

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20191887
Address: 1537 SW ARBOR FALLS DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Brandon Kalwei	Failed	Tuesday, November 05, 2019

Corrective Action Required:

- | | | |
|---|------|--|
| 1 | Misc | <ul style="list-style-type: none">- uncover front garage portal straps- anchor bolt needed on east side of garage where edges of sill plate meet- support plumbing in garage above door entrance- solid block heat chase at top plate and going into floor joist cavity, first floor- fireblock electrical penetrations In heat chase at bottom subfloor- fire block electrical penetration through top plate, left of fire place- protect piping at bottom plate, upstairs bathroom SW corner |
|---|------|--|

Ok to insulate

Comments: