

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20182733
Address: 2528 SW RIVER TRAIL RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Brandon Kalwei	Passed	Friday, November 15, 2019

Corrective Action Required:

1	Misc	-Clothes dryer exhaust wall needs to be 2x6 or firred out, cannot be in 2x4 wall or contorted** exhaust pipe is still contorted, needs to be original shape -Electrical penetration in return air at bottom of stairs going to basement needs to be fire protected -Fire block above tub at top plate in basement, not done properly. Air gap at top plate
---	------	--

Ok to insulate

Comments: