

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20191814
Address: 2943 SW ARBOR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Brandon Kalwei	Failed	Tuesday, November 19, 2019

Corrective Action Required:

1	Misc	- fire block dead space at top plate between front shower and master shower - missing hurricane strap above rear door - clothes dryer vent cannot be contorted from original shape - fire-block double walls in basement vertically every 10' - anchor beam posts in basement - fire block electrical penetrations at top plate in downstairs middle bathroom - fire block dead space at top plate, east wall in basement - fire block top plate at double walls in basement, south walls - over notched floor joist on south side of basement - fire block electrical penetration going through top plate, in south bathroom in basement, south wall - fire block top plate above sub panel - fire block at top plate east wall in west downstairs bedroom. Above entrance light switch - Do not insulate
---	------	--

Comments: