CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192706 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection	n:	Inspector:	Outcome:	Date:
Footing Inspection - Commercial John Borns		ial John Borns	Partial	Tuesday, November 19, 2019
Partial Co	rrection:			
1	Misc	OK TO POUR WHEN READY WALL FOOTING & INTEGRAL COLUMN FOOTINGS AT: A'/11.2 CCW TO A/8.5; A/8.5 TO 7.5/A'; 7.3/A.1 CCW TO 3.9/A; A/3.3 CCW TO A'/1.5; A'/11.2 TO 13/A' TO 12/E.5; UFER GROUNDING JUMPER AT 12.7/A.5; 12/E.5 TO I/12 TO I/9.1; I/9.1 to I/6.3;		
Partial Co	rrection:			
2	Misc		Y ISOLATED FOOTINGS AT FO /G; 11/H; 10/C; 10/D; 10/E; :	

Comments: