## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20183200

Address: 1706 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

**Above Ceiling Inspection** John Borns Failed Wednesday, November

20, 2019

Partial Correction:

1 Misc OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING SYSTEMS

@ FOLLOWING SPACES: A124; 126; 128; 130; 131; 132; A100; 102; 103; 104;

105; 106; 107; 108; 111; A115-118;

Corrective Action Required:

2 Misc FIRESTOP ALL RATED ASSEMBLIES:

OPENINGS THROUGH RATED WALLS & CEILINGS
 SLEEVES THROUGH RATED WALLS & CEILINGS
 FIRE COLLARS FOR PENETRATIONS BY PVC PIPE >2"

- REMOVE TAPE AT PENETRATIONS TO BE CAULKED

Corrective Action Required:

3 Misc REMOVE TEMPORARY WIRING & FIXTURES

Corrective Action Required:

4 Misc INSTALL ALL HVAC GRILLES AND DIFFUSERS. BAND FLEX INTERIOR & EXTERIOR

LAYERS INDEPENDENTLY.

Corrective Action Required:

5 Misc NEC 334-10 SECURING / SUPPORT OF MC ELECTRICAL CABLE: SECURE WITHIN

12" OF BOXES AND SUPPORT AT 6' MAX INTERVALS THEREAFTER. USE CLAMPS

THAT FASTEN MC IN PLACE WITHIN 12" OF BOX ENTRY.

CLOSE ALL ELECTRICAL BOXES.

**Comments:**