## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20192706 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspec	tion:	Inspector:	Outcome:	Date:
Footing Inspection - Commercial John Borns		Partial	Wednesday, November 20, 2019	
Partial	Correction:			
1	Misc			INTEGRAL COLUMN FOOTINGS
				3/A.1 CCW TO 3.9/A; A/3.3 CCW
		TO A'/1.5; A'/11.2 TO	D 13/A' TO 12/E.5; UFER G	ROUNDING JUMPER AT 12.7/A.5;
		12/E.5 TO I/12 TO I/9	9.1; I/9.1 to I/6.3; <b>I/6.3 TO</b>	) 1/4.7;
Partial	Correction:			
2	Misc	OK TO POUR WHEN	READY ISOLATED FOOTING	GS AT FOLLOWING LOCATIONS:
		11/C; 11/D; 11/E; 11	/F; 11/G; 11/H; 10/C; 10/D	D; 10/E; 10/F; 10/G; 10/H; <b>9/C;</b>
		9/D; 9/E; 9/F; 9/G; 9	)/H;	

**Comments:**