

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20192141
Address: 4410 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Brandon Kalwei	Failed	Tuesday, November 26, 2019

Corrective Action Required:

1	Misc	-Garage attic access clearance needs to be code compliant, less than 36" front top of framing to bottom of framing - run gas line to fireplace - fire block double wall at top plate separating kitchen and bathroom - properly fireblock double wall top plates in basement - fire block electrical penetrations through top floor above north basement bedroom egress window - over bored studs in downstairs bathroom -double joist hanger missing nails outside of furnace room and bottom of stairs in basement Do not insulate
---	------	---

Comments: