

DAILY FIELD REPORT

CLIENT:	Pearl Real Estate Company 919 N East Street Indianapolis, Indiana 46202	PROJECT:	Summit of West Pryor Apartments Lee's Summit, Missouri
ATTN:	Brad Richey	DATE:	11/6/19
WEATHER:	Sunny	CFS PERSONNEL:	M. Simpson
TEMPERATURE:	40-60	REPORT #:	19-1125-dr- 4

TYPE OF SERVICE BEING PERFORMED

SOILSFOUNDATIONSCONCRETEPLACEMENTCONCRETEREINFORCING STEELCONCRETECYLINDER PICK UP

DEVIATION FOUND: NO

DEVIATION CORRECTED:

ORIGINAL DEVIATION DATE:

WORK ACCOMPLISHED THIS DATE:

- Inspected footings for 7.6-A to 4.0-A
- All footings met required bearing capacity and size.

• Monitored placement of concrete for Ftgs 7.6-A to 4.0-A

- One set of 4 test cylinders were cast. Slump and temperature met job requirements.
- · Reinforcing steel verified to be in compliance with plans and specifications.

• Cylinder pick up of set 1759