

## DAILY FIELD REPORT

CLIENT:	Pearl Real Estate Company 919 N East Street Indianapolis, Indiana 46202	PROJECT:	Summit of West Pryor Apartments Lee's Summit, Missouri
ATTN:	Brad Richey	DATE:	11/13/19
WEATHER:	Sunny	CFS PERSONNEL:	M. Simpson
TEMPERATURE:	28-42	REPORT #:	19-1125-dr- 9

## TYPE OF SERVICE BEING PERFORMED

SOILSFOUNDATIONSCONCRETEPLACEMENTCONCRETEREINFORCING STEEL

**DEVIATION FOUND: NO** 

**DEVIATION CORRECTED:** 

**ORIGINAL DEVIATION DATE:** 

## WORK ACCOMPLISHED THIS DATE:

- Inspected footings for A.5 -12 to E.5-12
- · All footings met required bearing capacity and size.
- Monitored placement of concrete for Ftgs. A.5 -12 to E.5-12
- One set of 4 test cylinders were cast. Slump and temperature met job requirements.
- · Reinforcing steel verified to be in compliance with plans and specifications.
- Observed 12" of crusher rock material placed and compacted to correct elevation at lot number 8 (apartment excavation), adequate compaction was observed.