

DAILY FIELD REPORT

CLIENT:	Pearl Real Estate Company 919 N East Street Indianapolis, Indiana 46202	PROJECT:	Summit of West Pryor Apartments Lee's Summit, Missouri
ATTN:	Brad Richey	DATE:	11/6/19
WEATHER:	Sunny	CFS PERSONNEL:	M. Simpson
TEMPERATURE:	40-60	REPORT #:	19-1125-dr- 3

TYPE OF SERVICE BEING PERFORMED

SOILSFOUNDATIONSCONCRETEPLACEMENTCONCRETEREINFORCING STEELCONCRETECYLINDER PICK UP

DEVIATION FOUND: NO

DEVIATION CORRECTED:

ORIGINAL DEVIATION DATE:

WORK ACCOMPLISHED THIS DATE:

- · Inspected footings for Ftgs. 7.9-A to 7.6-A
- All footings met required bearing capacity and size.
- Monitored placement of concrete for Ftgs. 7.9-A to 7.6-A
- One set of 4 test cylinders were cast. Slump and temperature met job requirements.
- Reinforcing steel verified to be in compliance with plans and specifications.
- Cylinder pick up of set 1748.