CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182607 Address: 829 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assem	oly Inspection	John Borns	Partial	Wednesday, November 27, 2019
Partial Correct	ion:			
1 Mis	5C	OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT STAIRWELLWALLS INSIDE FACE AND SPACES BETWEEN JOISTS AT BACKSIDE:		
		NORTH STAIRWELL: BASEMENT LEVEL: 1ST LA 1ST FLOOR: 1ST LAYER; 2 2ND FLOOR: 1ST LAYER; 3RD FLOOR: 4TH FLOOR:	, ,	
		SOUTH STAIRWELL: 1ST FLOOR: 1ST LAYER; 2 2ND FLOOR: 1ST LAYER; 3RD FLOOR: 4TH FLOOR:	ND LAYER;	
Partial Correct	ioni		IERE PVC PIPE INTERRUPTS O LETED. USE ONLY LISTED FIRI	
2 Mis		OK TO COVER WHEN REA	DY 5/8" MOLD-RESISTANT FI	RECODE X GWB AT

ELEVATOR SHAFT WALLS ?INSIDE FACE AND? SPACES BETWEEN JOISTS AT BACKSIDE: BASEMENT LEVEL: 1ST FLOOR: 1ST LAYER; 2ND LAYER; 2ND FLOOR: **1ST LAYER;** 2ND FLOOR: 3RD FLOOR: 4TH FLOOR:

Comments: