## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20191957

Address: 930 NW BLUE PKWY, Unit:E, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

**Above Ceiling Inspection** John Borns Failed Tuesday, December 03,

2019

Partial Correction:

1 Misc OK TO COVER WHEN READY GWB CEILING / SOFFIT / BULKHEAD FRAMING +

ABOVE-CEILING SYSTEMS AT: EXAM 4

Corrective Action Required:

2 Misc ACT TILE AREAS: REMOVE TILE FOR INSPECTION

Corrective Action Required:

3 Misc ELECTRICAL WORK STILL IN PROGRESS. COMPLETE FOR INSPECTION.

Corrective Action Required:

4 Misc REMOVE TEMPORARY ELECTRICAL WIRING

Corrective Action Required:

5 Misc SUPPORT ALL LOW-VOLTAGE CONDUCTORS WITH HARDWARE DESIGNED FOR

PURPOSE. DO NOT SUPPORT FROM OTHER M/E/P SYSTEMS.

Corrective Action Required:

6 Misc REMOVE STRAP HANGERS AND ANY OTHER UNUSED HARDWARE

Corrective Action Required:

7 Misc NEC 334-10 SECURING / SUPPORT OF MC ELECTRICAL CABLE: SECURE WITHIN

12" OF BOXES AND SUPPORT AT 6' MAX INTERVALS THEREAFTER.

PLUG ANY UNUSED BOX OPENINGS.

Corrective Action Required:

8 Misc OBTAIN A/E LETTER ALLOWING USE OF FLEX DUCT AS RETURN AIR BOOTS. IF

ALLOWED, THEN ENSURE NONE ARE CONSTRICTED TO ACCOMODATE AIR

Λ/	IO۱	/[	٨л		NIT	г
ıv	ルノ	VГ	IVI	Г	IVI I	١.

CHECK ALL FLEX DUCT CONNECTIONS TO ENSURE BANDING IS PROPERLY DONE.

**Comments:**