## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20192706

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Footing Inspection - Commercial John Borns Partial Thursday, December

05, 2019

Partial Correction:

1 Misc OK TO POUR WHEN READY WALL FOOTING & INTEGRAL COLUMN FOOTINGS

AT: A'/11.2 CCW TO A/8.5; A/8.5 TO 7.5/A'; 7.3/A.1 CCW TO 3.9/A; A/3.3 CCW TO A'/1.5; A'/11.2 TO 13/A' TO 12/E.5; UFER GROUNDING JUMPER AT 12.7/A.5;

12/E.5 TO I/12 TO I/9.1; I/9.1 to I/6.3; I/6.3 TO I/4.7;

Partial Correction:

2 Misc OK TO POUR WHEN READY ISOLATED FOOTINGS AT FOLLOWING LOCATIONS:

11/C; 11/D; 11/F; 11/F; 11/G; 11/H; 10/C; 10/D; 10/F; 10/F; 10/G; 10/H; 9/C; 9/D; 9/E; 9/F; 9/G; 9/H; 8/C; 8/D; 8/E; 8/F; 8/G; 8/H; 7/C; 7/D; 7/E; 7/F; 7/G; 7/H; STEP FOOTING FROM FTG E/8 EAST TO ELEVATOR PIT SLAB; 6/C; 6/D; 6/E; 6/F; 6/G; 6/H; 5/C; 5/D; 5/E; FOOTINGS AND ELEVATOR PIT SLAB ON (5) FROM (F) TO (G.2); H/5; [4.5/C; 4.5/D; 4.5/E; 4.5/F; 4.3/C; 4.3/D; 4.3/E; 4.3/F; 4/C; 4/D; 4/E; 4/F; 4/G; 4/H; 3/C; 3/D; 3/E; 3/F; 3/G\*; 3/H\*; 2/C; 2/D; 2/E\*; 2/F;

2/G; 2/H;

2/E\*; 3/G\*; 3/H\*: CHECK BAR COUNT AND MAT SIZE

**Comments:**