

# Inspection Summary

---

Permit #: PRSUBD20193057, Development - Subdivision  
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>DE - Storm - Outlet Structure</b>	John Jackson	Partial	Thursday, December 19, 2019

Informational  
1

Outlet structure installed at 3+00 as per plans.

**Comments:**