

Inspection Summary

Permit #: PRSUBD20193057, Development - Subdivision
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Storm - Outlet Structure	John Jackson	Partial	Thursday, December 19, 2019

Informational
1

Outlet structure installed at Line A Sta. 3+00 as per plans 24"
CONC. FES w/ CUTOFF WALL LS STD DETAIL STM-5.

Comments: