## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20192706 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection	n:	Inspector:	Outcome:	Date:
Footing Ir	nspection - Commercia	l John Borns	Partial	Friday, December 20, 2019
Partial Correction:				
1		11/C; 11/D; 11/E; 11/F; 11/ 9/D; 9/E; 9/F; 9/G; 9/H; 8/C 7/H; STEP FOOTING FROM I 6/F; 6/G; 6/H; 5/C; 5/D; 5/E (F) TO (G.2); H/5; [4.5/C; 4.5	ISOLATED FOOTINGS AT FO G; 11/H; 10/C; 10/D; 10/E; 1 ; 8/D; 8/E; 8/F; 8/G; 8/H; 7/0 FTG E/8 EAST TO ELEVATOR ; FOOTINGS AND ELEVATOR 5/D; 4.5/E; 4.5/F; 4.3/C; 4.3/ ; 3/E; 3/F; 3/G*; 3/H*; 2/C; 3	0/F; 10/G; 10/H; 9/C; C; 7/D; 7/E; 7/F; 7/G; PIT SLAB; 6/C; 6/D; 6/E; PIT SLAB ON (5) FROM D; 4.3/E; 4.3/F; 4/C; 4/D;
Partial Correction:				
2		AT: A'/11.2 CCW TO A/8.5; TO A'/1.5; A'/11.2 TO 13/A'	WALL FOOTING & INTEGRA A/8.5 TO 7.5/A'; 7.3/A.1 CC\ TO 12/E.5; UFER GROUNDII .1 to I/6.3; I/6.3 TO I/4.7; I/4	W TO 3.9/A; A/3.3 CCW NG JUMPER AT 12.7/A.5;

Comments: