CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192706 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspe	ction:	Inspector:	Outcome:	Date:
Underslab Electrical Inspection - John Borns Commercial			Partial	Tuesday, December 31, 2019
Partia	l Correction:			
1	Misc	NO ISSUES FOUND ON UNDER-SLAB ELECTRICAL CONDUIT MATERIAL &		
		WORKMANSHIP. OK	TO COVER WHEN READY A	AT: NW CORNER OF BUILDING
		TO ~60' S/SE TWENTY-TWO 3" CONDUITS & TWO 2" CONDUITS;		
		G.C. AND E.C. TO EN	SURE LAYOUT IS CORRECT	OK TO COVER WHEN READY.

Comments: