CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182604 Address: 837 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Commercial		John Borns	Partial	Monday, January 06, 2020
Partial Correction:				
1	Misc	TO BE ENCLOSED AT:	DY WOOD FRAMED WALLS/C	EILINGS AND SYSTEMS
			SECOND FLOOR ABOVE FIRE RCED WHERE NOTCHED FOR	
		CEILING AT GARAGE #1 NO	ORTH 6';	
		WING SEPARATION FIREW	/ALLS AT:	
		LEFT WING: 4TH FLOOR; 3	RD FLR; 2ND FLR; 1ST FLR	
Partial Correction:				
2	Misc	OK TO PLACE GWB WHEN	READY AT CHASES BEHIND S	HOWERS AT:
		4TH FLOOR: LEFT WING; C	ENTER; [RIGHT WING	
		3RD FLOOR: LEFT WING; C	ENTER; [RIGHT WING	
		2ND FLOOR: LEFT WING; C		
		1ST FLOOR: LEFT WING; CE	ENTER; [RIGHT WING	
Partial Correction:				
3	Misc	OK TO FOAM AND INSULA	TE ABOVE CEILING AT:	
		4TH FLOOR: LEFT WING;		
Partial Correction:				
4	Misc	OK TO COVER WALLS AND	CEILINGS AT:	

		LEFT WING: 4TH FLOOR; ROUGH-IN; RC CHANNEL; RIGHT WING FIREWALL ABOVE CEILING @ ELEV #2 & UNITS N; 3RD FLOOR; ROUGH-IN; RC CHANNEL 2ND FLOOR; ROUGH-IN; RC CHANNEL		
		1ST FLOOR: ROUGH-IN @ UNITS ONLY INCLUDING 111, 119, 121; GARAGES, CORRIDOR, STORAGE RMS, JAN RM; RC CHANNEL @ UNITS ONLY; RC CHANNEL @ CEILINGS AT GARAGES, STORAGE, ELECT/MECH, JAN RMS; RC CHANNEL @ CEILINGS & WALLS AT CORRIDOR; OSB SHEATHING AT SHEAR WALL 6 AT SPRINKLER ROOM;		
		CENTER SECTION:		
		RIGHT WING:		
Partial Correction:				
5	Misc	OK TO COVER THREE WALLS AT STAIRWELLS:		
		AT 1ST FLOOR: STAIRWELLS 1, 2, 3, 4		
		AT 2ND FLOOR: STAIRWELLS 1, 4, 2, 3		
		AT 3RD FLOOR: STAIRWELLS 1, 4, 2, 3		
		AT 4TH FLOOR/TOWER: STAIRWELLS 1, 2, 3, 4		
Partial Correction:				
6	Misc	OK TO COVER WHEN READY:		
		LIGHT-GAUGE STEEL FRAMED CEILING FUR-DOWNS AT: (1)228; (1)229;		
		SPACE ABOVE BOTTOM CHORD OF JOISTS AT: BA IN MOTHER-IN-LAW UNIT @		
		RIGHT WING; VESTIBULES AT (1)211 & (1)217;		

Comments: