

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192706
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Footing Inspection - Commercial	John Borns	Partial	Thursday, January 09, 2020

Partial Correction:

1 Misc

OK TO POUR WHEN READY ISOLATED FOOTINGS AT FOLLOWING LOCATIONS:
11/C; 11/D; 11/E; 11/F; 11/G; 11/H; 10/C; 10/D; 10/E; 10/F; 10/G; 10/H; 9/C;
9/D; 9/E; 9/F; 9/G; 9/H; 8/C; 8/D; 8/E; 8/F; 8/G; 8/H; 7/C; 7/D; 7/E; 7/F; 7/G;
7/H; STEP FOOTING FROM FTG E/8 EAST TO ELEVATOR PIT SLAB; 6/C; 6/D; 6/E;
6/F; 6/G; 6/H; 5/C; 5/D; 5/E; FOOTINGS AND ELEVATOR PIT SLAB ON (5) FROM
(F) TO (G.2); H/5; [4.5/C; 4.5/D; 4.5/E; 4.5/F; 4.3/C; 4.3/D; 4.3/E; 4.3/F; 4/C; 4/D;
4/E; 4/F; 4/G; 4/H; 3/C; 3/D; 3/E; 3/F; 3/G*; 3/H*; 2/C; 2/D; 2/E*; 2/F; 2/G; 2/H;
B/11; B/10; B/9; B/8; A/8; **B/2; B/3; B/6; B/7;**

2/E*; 3/G*; 3/H*: CHECK BAR COUNT AND MAT SIZE

Partial Correction:

2 Misc

OK TO POUR WHEN READY WALL FOOTING & INTEGRAL COLUMN FOOTINGS
AT: A'/11.2 CCW TO A/8.5; A/8.5 TO 7.5/A'; 7.3/A.1 CCW TO 3.9/A; A/3.3 CCW
TO A'/1.5; A'/11.2 TO 13/A' TO 12/E.5; UFER GROUNDING JUMPER AT 12.7/A.5;
12/E.5 TO I/12 TO I/9.1; I/9.1 TO I/6.3; I/6.3 TO I/4.7; I/4.7 TO I/2; I/2 TO 1/I TO
1/D.7;

Comments: