

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20191899
Address: 1821 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Brandon Kalwei	Failed	Friday, January 10, 2020

Corrective Action Required:

1	Misc	-front exterior garage portal straps need to be uncovered to inspect - secure gas line to fireplace - joist hanger needed in south spare bedroom, west wall - protect outlet in air return, in wall between kitchen and master bedroom - joist hangers needed for east side rafters in kitchen, attaching to I beam - protect waterlines at bottom plate for clothes washer
---	------	--

Comments: