

## DAILY FIELD REPORT

CLIENT:	Pearl Real Estate Company 919 N East Street Indianapolis, Indiana 46202	PROJECT:	Summit of West Pryor Apartments Lee's Summit, Missouri
ATTN:	Brad Richey	DATE:	12/20/19
WEATHER:	Overcast	CFS PERSONNEL:	G. Kenyon
TEMPERATURE:	35-45	REPORT #:	19-1125-dr- 33

## TYPE OF SERVICE BEING PERFORMED

**CONCRETE** PLACEMENT

**DEVIATION FOUND: NO** 

**DEVIATION CORRECTED:** 

**ORIGINAL DEVIATION DATE:** 

WORK ACCOMPLISHED THIS DATE:

- · Monitored placement of concrete for Exterior wall 12/G.9 E, Columns B/8, 9, 10, 11 & A/8
- One set of 4 test cylinders were cast. Slump and temperature met job requirements. Air met job requirements.
- Reinforcing steel verified to be in compliance with plans and specifications.