

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20192617
Address: 2013 NE BLUESTONE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Passed	Thursday, January 16, 2020

Informational:

1 Misc

Just as an FYI. You should do the below:

- Protect plumbing throughout, mostly in basement bathrooms
- Stud shoe for studs bored than 60%
- Nail the girder truss together per truss detail
- Fb wall in basement from soffit
- Bonding connection of gas piping need to be accessible

I also saw a Dewalt saw out on the floor. I put the tool in the tub out-of-sight.

Comments: