

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191159
Address: 120 SW BLUE PKWY, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Concrete Walls and Columns Inspection	John Borns	Partial	Tuesday, January 21, 2020

Partial Correction:

1 Misc

OK TO CLOSE FORMS AND POUR WHEN READY C.I.P. WALLS: THREE CAISSON CHAMBER DIVIDER WALLS; WEST POOL WALL FROM NORTH ALONG WIDTH OF SURGE TANK; EAST POOL WALL NORTH 25'; REAR WALL OF CAISSON CHAMBERS; BUILDING FOUNDATION WALLS EAST OF WEST POOL WALL; BUILDING FOUNDATION WALLS EXCEPT AT PUMP PIT & SW 15' OF FILTRATION; **FRONT WALL OF CAISSONS;**

****SURGE TANK WALLS-OK. 2 ACCESS OPENINGS WILL BE CLOSED. PICTURE VERIFICATION WILL BE PROVIDED FOR NEXT INSPECTION**

Comments: