CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192706

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Foundation Inspection - John Borns Partial Thursday, January 23,

Commercial 2020

Partial Correction:

1 Misc OK TO POUR WHEN READY C.I.P. WALL & INTEGRAL COLUMNS AT:

12/H.5 TO I/12 TO I/10.4; N WALL; I/10.4 TO I/8.2; I/8.2 TO I/5.7; 8 LINE E TO G FOUNDATION WALL NORTH END IN CENTER; East wall - 5.6line to 1.1line; **1/B.2**

TO 1/C;

ENSURE KEYWAY AND WATERSTOP ARE CLEAR AND CLEAN AND WALL CHAIRS

ARE IN PLACE PRIOR TO BUTTONING-UP FORMS.

Partial Correction:

2 Misc OK TO POUR WHEN READY C.I.P. CONCRETE COLUMNS @ LOCATIONS:

5line @ E; 4line@E;

Comments: