CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182611 Address: 901 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Friday, January 24, 2020
Partial Correction:			
1 Misc	OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT STAIRWELLS INSIDE FACE & BACKSIDE PRE-ROCK BETWEEN JOISTS:		
	EAST STAIRWELL #1		
	BASEMENT LEVEL: 1ST LAYER; 2ND LAYER		
	1ST FLOOR: 1ST LAYER; 2ND LAYER		
	2ND FLOOR: 1ST LAYER; 2ND LAYER		
	3RD FLOOR:		
	4TH FLOOR:		
	WEST STAIRWELL #2		
	BASEMENT LEVEL: 2 LAYERS		
	1ST FLOOR: 1ST LAYER; 2ND LAYER		
	2ND FLOOR: 1ST LAY	'ER; 2ND LAYER	
	3RD FLOOR:		
	4TH FLOOR:		
Partial Correction:			
2 Misc	OK TO COVER WHEN ELEVATOR SHAFT:	I READY 5/8" MOLD-RESIS	TANT FIRECODE X GWB AT
	BETWEEN TRUSS JO	ISTS:	

BASEMENT LEVEL: BACKSIDE PRE-ROCK 2 LAYERS 1ST FLOOR: BACKSIDE PRE-ROCK 2 LAYERS 2ND FLOOR: **BACKSIDE PRE-ROCK 2 LAYERS** 3RD FLOOR: 4TH FLOOR:

Comments: