



1100 W Cambridge Circle Drive, Suite 700  
Kansas City, Kansas 66103  
913.627.9040

## DAILY FIELD REPORT

CLIENT: Pearl Real Estate Company  
919 N East Street  
Indianapolis, Indiana 46202

PROJECT: Summit of West Pryor  
Apartments  
Lee's Summit, Missouri

ATTN: Brad Richey

DATE: 12/6/19

WEATHER: Sunny

CFS  
PERSONNEL: M. Simpson

TEMPERATURE: 30-50

REPORT #: 19-1125-dr- 24

---

### TYPE OF SERVICE BEING PERFORMED

**SOILS** COMPACTION MONITORING

**DEVIATION FOUND: NO**

**MASONRY** GROUT / REINFORCING STEEL

**DEVIATION CORRECTED:**

**CONCRETE** REINFORCING STEEL

**ORIGINAL DEVIATION DATE:**

**CONCRETE** CYLINDER PICK UP

---

### WORK ACCOMPLISHED THIS DATE:

- Observed 8" of type 5 rock and geo grid placed for the parking lot West of the apartment building on lot number 8, proof-roll pending as per city of Lee's Summit specifications.
- Monitored placement of grout and inspected reinforcing steel at A line/6.0 - 9.7 TO 10.6, (97.4 - 103.75 AFF) Wall is grouted solid.
- Reinforcing steel verified to be in compliance with plans and specifications.
- Inspected reinforcing steel placement for Walls from G.10-2 to 10.1-J
- Reinforcing steel verified to be in compliance with plans and specifications.
- Cylinder pick up of sets 1964