

DAILY FIELD REPORT

CLIENT:	Pearl Real Estate Company 919 N East Street Indianapolis, Indiana 46202	PROJECT:	Summit of West Pryor Apartments Lee's Summit, Missouri
ATTN:	Brad Richey	DATE:	12/2/19
WEATHER:	Overcast	CFS PERSONNEL:	M. Simpson / G. Kenyon
TEMPERATURE:	30-50	REPORT #:	19-1125-dr- 20

DEVIATION FOUND: NO

DEVIATION CORRECTED:

ORIGINAL DEVIATION DATE:

TYPE OF SERVICE BEING PERFORMED

SOILSFOUNDATIONSMASONRYGROUTMASONRYREINFORCING STEELCONCRETECYLINDER PICK UP

WORK ACCOMPLISHED THIS DATE:

M. Simpson

- Monitored placement of grout and inspected reinforcing steel at A line/7.9 to 9.2, (92.8 96.8 AFF) Wall is grouted solid.
- Reinforcing steel verified to be in compliance with plans and specifications.
- Inspected footings for 4.3/C, D, E, F; 4.5/C, D, E, F; 4.1/C, D, E, F, G & G.9.
- · All footings met required bearing capacity and size.

G. Kenyon

• Cylinder pick up of set 1926.