

## DAILY FIELD REPORT

CLIENT:	Pearl Real Estate Company 919 N East Street Indianapolis, Indiana 46202	PROJECT:	Summit of West Pryor Apartments Lee's Summit, Missouri
ATTN:	Brad Richey	DATE:	12/11/19
WEATHER:	Sunny	CFS PERSONNEL:	M. Simpson
TEMPERATURE:	25-50	REPORT #:	19-1125-dr- 27

## TYPE OF SERVICE BEING PERFORMED

MASONRY	GROUT
MASONRY	REINFORCING STEEL
CONCRETE	REINFORCING STEEL
CONCRETE	CYLINDER PICK UP

WORK ACCOMPLISHED THIS DATE:

- Monitored placement of grout and inspected reinforcing steel at CMU walls A/4.3 to 1.8, elevation 92.8 to 96.8 (grouted solid)
- · Reinforcing steel verified to be in compliance with plans and specifications.
- · Inspected reinforcing steel placement for Wall F-12 G.10-12
- · Reinforcing steel verified to be in compliance with plans and specifications.
- Cylinder pick up of set 1993.

**DEVIATION FOUND: NO** 

DEVIATION CORRECTED:

**ORIGINAL DEVIATION DATE:**