

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192706  
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Foundation Inspection - Commercial</b>	John Borns	Partial	Friday, February 07, 2020

Partial Correction:

1 Misc

OK TO POUR WHEN READY C.I.P. WALL & INTEGRAL COLUMNS AT:  
12/H.5 TO I/12 TO I/10.4; N WALL; I/10.4 TO I/8.2; I/8.2 TO I/5.7; 8 LINE E TO G  
FOUNDATION WALL NORTH END IN CENTER; East wall - 5.6line to 1.1line; 1/B.2  
TO 1/C; 1/C TO 1/E.2; 1/E.2 TO 1/J TO J/1.3; **FROM J/1.3 NORTH TO COMPLETE  
EAST WALL AND ENTIRE C.I.P. PERIMETER WALL;**

ENSURE KEYWAY AND WATERSTOP ARE CLEAR AND CLEAN AND WALL CHAIRS  
ARE IN PLACE PRIOR TO BUTTONING-UP FORMS.

Partial Correction:

2 Misc

OK TO POUR WHEN READY C.I.P. CONCRETE COLUMNS @ LOCATIONS: 5 line @  
E; 4 line @ E;

**Comments:**