

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20192722

Address: 392 NW CHIPMAN RD, Unit:ES, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial	Joe Starlin	Partial	Thursday, February 06, 2020

Informational:

1 Misc

2-6-20 They have set pull boxes 2,8,and 10 and are digging at the north west corner. They have forms set on the north west corner and are having issues with pole placement on the north east corner. There appears to be utility's in the way as well as a storm pipe were the pole was marked to go. ESS will be reaching out to Evergy for overhead clearance.

Comments: