## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20192982 Address: 840 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial		John Borns	Partial	Tuesday, February 18, 2020
Partial Cor	rection:			
1	Misc	FOLLOWING LOCATIONS FROM (4) TO (5); THREE 1 FROM (6) TO (8); FIVE 1" FROM (7) TO (9); ONE 1" FROM (X) TO (Y); ONE 1" FROM (13) TO (16); TWO (18) TO (19); SEVEN 4", O NORTH TO SERVICE EQUI	ADY BURIED CONDUIT FOR SIT : ONE 1" FROM (1) TO (2); TW L" FROM (2) TO (6); TWO 1" FR FROM (2) TO (6); TWO 1" FR FROM (10) TO (12); ONE 1" FR FROM (X) TO (Y); FOUR 1" FR 1" FROM SW CORNER OF BLE NE 1-1/4", THREE 1" FROM M PMENT AT C/2; TWO 4" FROM E 3/4" + TWO 1" + ONE 2" FRC OCATION;	O 1" (2) TO (3); ONE 1" ROM (6) TO (7); TWO 1" OM (6) TO (13); ONE 1" ROM (9) TO (12); ONE 1" OM (X) TO (Y); ONE 1" OG TO (18); ONE 1" FROM IDP TO EXTERIOR THEN M UNDER FOOTING AT
Partial Cor	rection:			
2	Misc	OK TO POUR WHEN REA 12 AT EAST PARKING LO	DY LIGHT POLE BASES AT FOL T;	LOWING LOCATIONS:

Comments: