CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192982 Address: 840 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial		John Borns	Partial	Wednesday, February 19, 2020
Partial Cor	rection:			
1	Misc	FOLLOWING LOCATIONS: FROM (4) TO (5); THREE 1' FROM (6) TO (8); FIVE 1" F FROM (7) TO (9); ONE 1" F FROM (X) TO (Y); ONE 1" F FROM (13) TO (16); TWO 1 (18) TO (19); SEVEN 4", ON NORTH TO SERVICE EQUIP	DY BURIED CONDUIT FOR SIT ONE 1" FROM (1) TO (2); TW(' FROM (2) TO (6); TWO 1" FR ROM (2) TO (6); TWO 1" FR ROM (2) TO (12); ONE 1" FR ROM (X) TO (Y); FOUR 1" FRC " FROM SW CORNER OF BLD IE 1-1/4", THREE 1" FROM M PMENT AT C/2; TWO 4" FROM 3/4" + TWO 1" + ONE 2" FRO CATION;	O 1" (2) TO (3); ONE 1" ROM (6) TO (7); TWO 1" M (6) TO (13); ONE 1" ROM (9) TO (12); ONE 1" OM (X) TO (Y); ONE 1" OF TO (18); ONE 1" FROM DP TO EXTERIOR THEN 4 UNDER FOOTING AT
Partial Cor	rection:			
2	Misc	OK TO POUR WHEN READ TWELVE AT EAST PARKING	Y LIGHT POLE BASES AT FOLL 5 LOT; TWO AT WEST LOT	OWING LOCATIONS:

Comments: