CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192982

Address: 840 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Underground Electrical John Borns Partial Thursday, February 27,

Inspection - Commercial 2020

Partial Correction:

1 Misc OK TO COVER WHEN READY BURIED CONDUIT FOR SITE ELECTRICAL SYSTEM AT

FOLLOWING LOCATIONS: ONE 1" FROM (1) TO (2); TWO 1" (2) TO (3); ONE 1" FROM (4) TO (5); THREE 1" FROM (2) TO (6); TWO 1" FROM (6) TO (7); TWO 1" FROM (6) TO (8); FIVE 1" FROM (2) TO (6); TWO 1" FROM (6) TO (13); ONE 1" FROM (7) TO (9); ONE 1" FROM (10) TO (12); ONE 1" FROM (9) TO (12); ONE 1" FROM (X) TO (Y); ONE 1" FROM (X) TO (Y); FOUR 1" FROM (X) TO (Y); ONE 1" FROM (13) TO (16); TWO 1" FROM SW CORNER OF BLDG TO (18); ONE 1" FROM (18) TO (19); SEVEN 4", ONE 1-1/4", THREE 1" FROM MDP TO EXTERIOR THEN NORTH TO SERVICE EQUIPMENT AT C/2; TWO 4" FROM UNDER FOOTING AT B/3 THEN W TO A/3; FIVE 3/4" + TWO 1" + ONE 2" FROM UNDER FOOTING AT B/3 N TO GENERATOR LOCATION; SEVEN 4" PVC FROM SWITCHGEAR OUTSIDE NW CORNER OF BUILDING TO 80' TOWARD TRANSFORMER LOCATION;

Partial Correction:

2 Misc OK TO POUR WHEN READY LIGHT POLE BASES AT FOLLOWING LOCATIONS:

TWELVE AT EAST PARKING LOT; TWO AT WEST LOT

Comments: