## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20192982 Address: 840 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                                       |           | Inspector:   | Outcome:   | Date:  |
|---|-----------|--|--|--|
| Underground Electrical<br>Inspection - Commercial |           | John Borns   | Partial  | Friday, February 28,<br>2020   |
| Partial Co  | rrection: |  |  |  |
| 1   | Misc      | FOLLOWING LOCAT<br>FROM (4) TO (5); TH<br>FROM (6) TO (8); FIN<br>FROM (7) TO (9); ON<br>FROM (7) TO (9); ON<br>FROM (13) TO (16);<br>(18) TO (19); SEVEN<br>NORTH TO SERVICE<br>B/3 THEN W TO A/3<br>B/3 N TO GENERATO<br>NW CORNER OF BU | IONS: ONE 1" FROM (1) TC<br>REE 1" FROM (2) TO (6); TV<br>/E 1" FROM (2) TO (6); TW<br>/E 1" FROM (10) TO (12); C<br>IE 1" FROM (X) TO (Y); FOU<br>TWO 1" FROM SW CORNE<br>4", ONE 1-1/4", THREE 1"<br>EQUIPMENT AT C/2; TWO<br>; FIVE 3/4" + TWO 1" + ON<br>DR LOCATION; SEVEN 4" P | FOR SITE ELECTRICAL SYSTEM AT<br>0 (2); TWO 1" (2) TO (3); ONE 1"<br>WO 1" FROM (6) TO (7); TWO 1"<br>O 1" FROM (6) TO (13); ONE 1"<br>ONE 1" FROM (9) TO (12); ONE 1"<br>JR 1" FROM (X) TO (Y); ONE 1"<br>R OF BLDG TO (18); ONE 1" FROM<br>FROM MDP TO EXTERIOR THEN<br>4" FROM UNDER FOOTING AT<br>IE 2" FROM UNDER FOOTING AT<br>VC FROM SWITCHGEAR OUTSIDE<br>RANSFORMER LOCATION, THEN |
| Partial Co  | rrection: |  | SI ORMER LOCATION,   |  |
| 2   | Misc      |  | READY LIGHT POLE BASES<br>RKING LOT; TWO AT WES  | AT FOLLOWING LOCATIONS:<br>T LOT   |

Comments: