## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20192670

Address: 920 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

**Rated Assembly Inspection** John Borns Failed Friday, February 28,

2020

Partial Correction:

1 Misc OK TO COVER WHEN READY COMPONENTS OF RATED ASSEMBLIES AT:

WALL ON (3) SOUTH FACE ONE LAYER 5/8" TYPE X GWB; 2ND LAYER OK TO TAPE, MUD AND FIRESTOP AFTER SCREWS ARE ADDED AS POINTED OUT;

WALL ON (5) SOUTH FACE ONE LAYER 5/8" TYPE X GWB;

Corrective Action Required:

2 Misc DEMISING WALL GWB NOT SCREWED PER UL AT BOTTOM PLATE.

MECHANICAL ROOM NOT ACCESSIBLE FOR GWB INSPECTION.

**Comments:**