

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192706
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underslab Electrical Inspection - Commercial	John Borns	Partial	Friday, February 28, 2020

Partial Correction:

1 Misc

NO ISSUES FOUND ON UNDER-SLAB ELECTRICAL CONDUIT MATERIAL & WORKMANSHIP. OK TO COVER WHEN READY AT: NW CORNER OF BUILDING TO ~60' S/SE TWENTY-TWO 3" CONDUITS & TWO 2" CONDUITS; FIVE 3" SOUTH TO (7) AT METER BANK 2B; ONE 3" FROM NW CORNER TO W/I 20' OF ELEVATOR C; SEVEN 3" & TWO 2" FROM NW CORNER TO F/12; **XXX RE-ROUTED FROM XXX TO B2A AT A/7.5; SEVEN 3" & TWO 2" FROM SW CORNER TO E SIDE OF COLUMN X/Y;**

G.C. AND E.C. TO ENSURE LAYOUT IS CORRECT. OK TO COVER WHEN READY.

Comments: