

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRCOM20192706  
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Underslab Electrical Inspection - Commercial</b>	John Borns	Partial	Monday, March 02, 2020

Partial Correction:

1 Misc

NO ISSUES FOUND ON UNDER-SLAB ELECTRICAL CONDUIT MATERIAL & WORKMANSHIP. OK TO COVER WHEN READY AT: NW CORNER OF BUILDING TO ~60' S/SE TWENTY-TWO 3" CONDUITS & TWO 2" CONDUITS; FIVE 3" SOUTH TO (7) AT METER BANK 2B; ONE 3" FROM NW CORNER TO W/I 20' OF ELEVATOR C; SEVEN 3" & TWO 2" FROM NW CORNER TO F/12; **SEVEN 3" & TWO 2" RE-ROUTED FROM F/12 TO B2A AT A/7.5; SEVEN 3" & TWO 2" FROM 1/A.5 TO E SIDE OF COLUMN 1/F;**

G.C. AND E.C. TO ENSURE LAYOUT IS CORRECT. OK TO COVER WHEN READY.

Comments: