

1100 W Cambridge Circle Drive

Suite 700

Kansas City, Kansas 66103

913.627.9040

2121 Moodie Road Lawrence, Kansas 66046 2011 NW Topeka Blvd Topeka, Kansas 66608

785.856.9600 785.270.6447

DAILY FIELD REPORT

CLIENT: Pearl Real Estate Company PROJECT: Summit of West Pryor

919 N East Street Apartments

Indianapolis, Indiana 46202 Lee's Summit, Missouri

ATTN: Brad Richey DATE: 2/25/20

CFS

WEATHER: Overcast PERSONNEL: M. Simpson

TEMPERATURE: 29-45 REPORT #: 19-1125-dr- 81

TYPE OF SERVICE BEING PERFORMED

SOILS COMPACTION MONITORING DEVIATION FOUND: NO

MASONRY GROUT / REINFORCING STEEL DEVIATION CORRECTED:

CONCRETE REINFORCING STEEL ORIGINAL DEVIATION DATE:

WORK ACCOMPLISHED THIS DATE:

- · Monitored placement and compaction of fill for Exterior wall back fill from 1 line/A to J
- Monitored placement of grout and inspected reinforcing steel at Elevator" A" shaft walls from elevation 88.00 to 92.00
- Reinforcing steel verified to be in compliance with plans and specifications.
- · Inspected reinforcing steel placement for Exterior wall columns at J line/11.6,11.2,10.6,10.4,9.6 & 9.2. (top 2' col. Caps)
- · Water stop system installed applied to exterior walls from 1 line/A to J