

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20182607  
Address: 829 NW DONOVAN RD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	John Borns	Partial	Tuesday, March 03, 2020

Partial Correction:

1	Misc	OK TO HANG GWB AT STAIRWELL FACE AND BACKSIDE BETWEEN JOISTS AT DOUBLE-WYTHE STAIRWELL WALLS:  SOUTH STAIR #1: FACE AND BACKSIDE BETWEEN JOISTS AT DOUBLE-WYTHE STAIRWELL WALLS 1ST FLOOR, 2ND FLOOR, 3RD FLOOR, 4TH FLOOR; BASEMENT NORTH & EAST WALLS; <b>LOW CEILINGS AT 4TH FLR;</b>  NORTH STAIR #2: FACE AND BACKSIDE BETWEEN JOISTS AT DOUBLE-WYTHE STAIRWELL WALLS: BASEMENT LEVEL; 1ST FLOOR; 2ND FLOOR; 3RD FLOOR; <b>LOW CEILINGS AT 4TH FLR;</b>
---	------	--

Partial Correction:

2	Misc	OK TO COVER CEILINGS, WALLS AT: WALLS ONLY AT MECH / ELEVATOR MACH RMS AT BASEMENT; STAIRWELL 1 AT BASEMENT NORTH
---	------	--

Partial Correction:

3	Misc	OK TO COVER WHEN READY FRAMING & SYSTEMS TO BE ENCLOSED AT <b>UNDERSIDE OF BALCONY PLATFORMS AT: 4TH, 3RD, 2ND, 1ST FLOORS</b>
---	------	--

Comments: