CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20190654

Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 640812020 NW OBRIEN RD, LEES SUMMIT, MO 64081500 NW PRYOR RD, LEES SUMMIT, MO 64081450 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
DE - Sanitary Sewer - Air Test		Ronald Paynter	Partial	Friday, March 06, 2020
Informational:				
1	Misc	The following sanitary lines passed their air test: manhole existing 28-208 to 1-1, 1-1 to 1-2, 1-2 to 1-3, 1-3 to 1-4, and 1-4 to 1-5. RP 1-7-2020		
Informational:				
2	Misc	The following sanitary lines passed their air test. Manholes 1-5 to 1-6, 1-6 to 1-7, 1-7 to 3-1 and 3-1 to 3-2. RP 2-7-20		
Informational:				
3	Misc	The following sanitary lines passed their air test: 1-7 to 1-8, 1-8 to 1-9, 1-9 to 1-10, 1-10 to 1-11, 1-11 to 1-12, 1-12 to 1-13 and 1-10 to 4-1. RP 3-5-20		
Informational:				
4	Misc	- ,	es passed their air test: 1-7 1-12, 1-12 to 1-13 and 1-10 t	
Corrective Action Required:				
5	Misc	• ,	e failed the air test: 8-1 to 8 aused the failed test. We w	
Informational:				
6	Misc	The following sanitary lin 8-4, 8-4 to 8-5, 8-5 to 8-6 a	es passed their air test: 8-0 nd 8-6 to 8-7. RP 3-6-20	to 8-1, 8-2 to 8-3, 8-3 to

Comments: