

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20192895
Address: 120 NW MACKENZIE DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mark Harding	Failed	Thursday, March 05, 2020

Corrective Action Required:

1	Misc	-Framing over bedroom 4 # ceiling and roof framing install per plans. (see Denis) - install perlins over bed 2-3. -First floor fire stop garage walls and chase from jost space. -Firestop flue/ heat chase 2nd. -protection Plate gas line studio basement ceiling -> -Secure gas line at fireplace (on both) -Stud under dlb header closet under lvl
---	------	---

Comments: