## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20192706

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

**Footing Inspection -** Mark Harding Partial Thursday, March 12,

Commercial 2020

Partial Correction:

1 Misc OK TO POUR WHEN READY ISOLATED FOOTINGS AT FOLLOWING LOCATIONS:

11/C; 11/D; 11/E; 11/F; 11/G; 11/H; 10/C; 10/D; 10/E; 10/F; 10/G; 10/H; 9/C; 9/D; 9/E; 9/F; 9/G; 9/H; 8/C; 8/D; 8/E; 8/F; 8/G; 8/H; 7/C; 7/D; 7/E; 7/F; 7/G; 7/H; STEP FOOTING FROM FTG E/8 EAST TO ELEVATOR PIT SLAB; 6/C; 6/D; 6/E; 6/F; 6/G; 6/H; 5/C; 5/D; 5/E; FOOTINGS AND ELEVATOR PIT SLAB ON (5) FROM (F) TO (G.2); H/5; [4.5/C; 4.5/D; 4.5/E; 4.5/F; 4.3/C; 4.3/D; 4.3/E; 4.3/F; 4/C; 4/D; 4/E; 4/F; 4/G; 4/H; 3/C; 3/D; 3/E; 3/F; 3/G; 3/H; 2/C; 2/D; 2/E; 2/F; 2/G; 2/H; B/11; B/10; B/9; B/8; A/8; B/2; B/3; B/6; B/7; B/4; B/4.3; B/4.5; B/5;

A/4.1; A/4.3; A/4.5; A/5; A/9;

EXTERIOR COLUMN PIERS O LINE-N @ 5.6-7.3

**Partial Correction:** 

2 Misc OK TO POUR WHEN READY WALL FOOTING & INTEGRAL COLUMN FOOTINGS

AT: A'/11.2 CCW TO A/8.5; A/8.5 TO 7.5/A'; 7.3/A.1 CCW TO 3.9/A; A/3.3 CCW

TO A'/1.5; A'/11.2 TO 13/A' TO 12/E.5; UFER GROUNDING JUMPER AT

12.7/A.5; 12/E.5 TO I/12 TO I/9.1; I/9.1 to I/6.3; I/6.3 TO I/4.7; I/4.7 TO I/2; I/2

TO 1/I TO 1/D.7;

OK TO POUR FOOTING & COLUMN FOOTING GRID LINE 1 E TO

B & C; REMAINDER OF PERIMETER FOOTING AT A-8'/1.3 CCW TO B.3/0.5;

## **Comments:**