

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192670
Address: 920 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Mark Harding	Partial	Thursday, March 12, 2020

Partial Correction:

1	Misc	OK TO COVER WHEN READY COMPONENTS OF RATED ASSEMBLIES AT: WALL ON (3) SOUTH FACE ONE LAYER 5/8" TYPE X GWB; 2ND LAYER OK WALL ON (5) SOUTH FACE ONE LAYER 5/8" TYPE X GWB;
---	------	--

vitaman store south wall 2nd layer, caulk all penetrations for above ceiling .

Corrective Action Required:

2	Misc	DEMISING WALL GWB NOT SCREWED PER UL AT BOTTOM PLATE.
---	------	---

MECHANICAL ROOM FOR GWB INSPECTION.- 1ST LAYER INSIDE & OUT.

Comments: